

# PEI Inspection Report

Address: 4-1-102, Hanchengqu, Tiantai Aoyuan, Chengyang District, Qingdao City, Shandong Province, China. Post Code: 266100. Tel: +86-532-8679-3119 Mobile: +86-137-3090-1204  
 Fax: +86-532-8965-2010. Email: syin@peichina.com, yinxiongzhi@gmail.com  
 Web: www.peichina.com Skype: simonyinchina

Page 1: Main page

<b>General Comments:</b>						
<b>Passed 100% inspection.</b>						
See the details below (total 7 pages).						
<b>Inspection Company</b>		PEI Inspection Services Ltd				
<b>Inspected by</b>		Wang, Lisa		<b>Report Date:</b>		9-19-07
<b>Inspection Date</b>		9-17, 9-18, 9-19-07		<b>Reported by:</b>		Wang
				<b>Customer:</b>		
				<b>Vendor:</b>		
<b>PO #</b>		<b>Item #</b>	<b>Desc./Color</b>	<b>PO Q'ty</b>	<b>Rec'd Q'ty</b>	<b>Date Rec'd</b>
195179		34752	9.5 "TOUR STAFF BAG	250	250	9-17, 9-18, 9-19-07
195179		34752	9.5 "TOUR STAFF BAG	100	100	9-17, 9-18, 9-19-07
<b>Ship to</b>	<b>USA</b>		<b>Total</b>	350	350	
<b>Lot/order#:</b>						
			<b>Insp. tool:</b>		Visual	
<b>Should Insp. Qty:</b>		<b>Actual Insp Qty</b>	<b>Qty Pass</b>	<b>Qty Reject</b>	<b>Pass or Fail?</b>	<b>100% Full inspection</b>
350		350	246	104	PASS	
<b>Categories for Rejection:</b>	<b>In Chinese</b>		<b>Q'ty Rejected</b>	<b>Remarks</b>	<b>Corrected or not</b>	
1 Dirty/Soiled	脏		20		Yes	
2 Fabric holes/flaws	布料有洞或不良		1	Holes on mesh	Yes	
3 Wrong Fabric	布料用错					
4 Wrong Embroidery	车花错					
5 Wrong Webbing	织带错					
6 Open seams/Bad stitching	漏包或车线不良					
7 Wrong Zipper Pulls	拉链头错		6	Zipper pull falls off.	Yes	
8 Wrong Zipper Tape	拉链布错					
9 Excessive Wrinkling	皱纹过多					
10 Handle Issues	手把问题					
11 Missing/Faulty Snaps	五金缺失或不良		1	Rivet is missing on top binding.	Yes	
12 Hood Issues	袋帽问题					
13 Sling Issues	肩带问题					
14 Untrimmed Thread	线头未剪					
15 Nameplate Issues	招牌问题					
16 Bad Sling Chape	招牌贴不良					
17 Defective Stand	脚架不良					
18 Defective Divider/Soft Cover	分格不良		8	Fiber glass comes out.	Yes	
19 Crooked top	袋头不正					
20 Other	其他					
	a)		17	The top front magnetic pocket could not cover well.	Yes	
	b)		34	Fraying embroidery	Yes	
	c)		14	The top front nameplate is dirty.		
	d)		1	Hang tag is missing.	Yes	
	e)		1	Hood is missing.	Yes	
	f)		1	Sling is missing.	Yes	
	g)					
21 Wrong/missing UPC, hang tag, carton marking, origin label and bottom stamp	条形码,挂卡,箱唛,产地唛或袋底烙印 错或缺					
	a)					
	b)					

# PEI Inspection Report

page 2: Approved Sample



# PEI Inspection Report

page 3: Special Instructions

### Special Instruction:



### Real images on this PO



Coal chute is stitched inward and we did not find hanging zippers.

Conformed or not

Conformed

# PEI Inspection Report

page 4: Rejection category 1-8

Category 1 Dirty.



Category 7 Zipper pull is easy to get off.



# **PEI** Inspection Report

page 5: Rejection category 9-16

Category 11

Rivet is missing on the top binding.



# PEI Inspection Report

page 6: Rejection category 17-20

Category 18

The fiber glass comes out.



Category 20)f

Hood is missing.



Category 20)d

Hang tag is missing.



Category 20)e

Sling is missing.



# PEI Inspection Report

## 1 UPC

### Specs

Model Number : 34752

UPC: 641684347526

### Actual images on this PO



Conformed or not Conformed

## 2 Hang tag

### Specs




### Actual images on this PO



Conformed or not Conformed

## 3 Carton marking

### Specs



### Actual images on this PO



Conformed or not Conformed